



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 07/09/2014


Reviewed 

Mine Name: Bohman Ranch	Permit Number: S/029/0006	Mine Status: Active
Operator Name: Bohman Rock LLC.	Inspection Date: 07/31/2013	Permit Fees: Delinquent
Inspector(s): L. Heppler	Inspection Time: 3:00 PM	Bond Amount: \$500
Attendee(s): Brent Bohman	Weather: Sunny, Dry	Bond Escalation: 08/21/2012
Inspection Purpose: Routine annual inspection		Prior Inspection: 11/30/2010

Conclusions and Recommendations

Overall operator understands resource conservation and has mined in a responsible manner. Bond amount is not sufficient for a 3rd party reclamation. Bond amount is past due for escalation and permit fees are past due. Surface rights are controlled by Operator and there has been no history of complaints to the Division. OGM to continue annual inspections and monitor the site when in the area

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Operator is delinquent in multiple year annual permit fees. Bond escalation is past due as shown above.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> No deficiencies were noted - project is gated	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No erosional problems noted, nor was there any evidence of any erosional problems.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> No deleterious materials were noted on site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were maintained and in fair condition.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection, several older mining areas have been reclaimed.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection, but mining was all near surface	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> Overall site vegetation is excellent	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Brent Bohman

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M029-Morgan/S0290006-BohmanRanch/inspections/INSP-07312013.pdf



Current Mining Area



Current Mining Area



Lower Sand and Gravel



Reclaimed Area